PHOTOGRAPHS

Photo 1. Aerial view of boat harbour and spoil dump during construction - 6 October 1987 (Photo QNPWS) 63

Photo 2. Aerial view of completed spoil dump showing silt plume moving southeastwards along shoreline - November 1987 (Photo QNPWS) 63

Photo 3. Overflow from settling pond during early stage of dredging - 18(?) September 1987 (Photo Alan Smith) 65

Photo 4. Overflow from settling pond/spoil dump during late stage of dredging - 28-29(?) October 1987 (Photo Alan Smith) 65

Photo 5. Aerial view of spoil dump shortly after completion of boat harbour construction - 7 December 1987 (Photo QNPWS) 67

Photo 6. Silt scarp and spoil dump beach south of jetty in vicinity of station 2 - 4 April 1989 (Photo J.L.F. Hacker) 69

Photo 7. Erosion scarp and shingle on beach face at southern end of spoil dump in vicinity of station 1 - 16 December 1988 (Photo J.S. Jell) 71

Photo 8. Interbedded layers of silt, sand and coarser material in vicinity of station 1 - 16 December 1988 (Photo J.S. Jell) 71

Photo 9. Waves breaking on spoil dump and creating a silt plume - 6 April 1989 (Photo J.L.F. Hacker) 73

Photo 10. Silt plume generated from spoil dump beach - 6 April 1989 (Photo J.L.F. Hacker) 73

Photo 11. Silt plume north of jetty following wave attack and mechanical movement of beach material to protect jetty - 29 May 1989 (Photo Andrew Flowers) 75

Photo 12. Localised silt plume generated by excavator working in boat harbour - 19 February 1988 (Photo QNPWS) 75

Photo 13. Silt plume generated by dredge working in boat harbour - 21 September 1987 (Photo QNPWS) 77

Photo 14. Silt plumes from dredge and spoil dump extending over southern reef flat - 23 October 1987 (Photo QNPWS) 77

Photo 15. Silt covered beach rock on southern side of island - 10 March 1988 (Photo QNPWS) 79

Photo 16. Western end of beach rock near spoil dump showing silt remaining on lower levels of rock - 1 December 1990 (Photo J.S. Jell) 79

Photo 17. Dried algae-encrusted mud on beach rock - May 1988. (Photo J.S. Jell) 81

Photo 18. Vegetation on spoil dump - 1 December 1990 (Photo J.S. Jell) 81



Photo 1. Aerial view of boat harbour and spoil dump during construction - 6 October 1987. (Photo QNPWS)

Photo 2. Aerial view of completed spoil dump showing silt plume moving southeastwards along shoreline - November 1987. (Photo QNPWS)