

TABLE OF CONTENTS

Executive Summary.....	xi
------------------------	----

PART ONE Short term monitoring and environmental effect

1. INTRODUCTION	1
2. HERON ISLAND BOAT HARBOUR AND ITS GEOMORPHIC SETTING	3
2.1 Works Constructed Prior to 1987.....	3
2.2 Boat Harbour Enlargement Works 1987.....	3
2.3 Geomorphic Setting of Heron Island.....	4
3. INVESTIGATIONS	6
3.1 Objectives of Monitoring Programme	6
3.2 Field Work	6
3.3 Sedimentological Analyses.....	7
3.4 Surveys of Spoil Dump Size and Shape	9
3.5 Hydraulic and Meteorological Data Analyses.....	10
4. RESULTS OF ANALYSES	13
4.1 Nature and Quantity of Material in Spoil Dump.....	13
4.1.1 The Spoil Dump	13
4.1.2 Subsurface Investigations of Spoil Dump.....	13
4.1.3 Nature of Subsurface Materials.....	14
4.1.4 Quantity of Material in Spoil Dump.....	15
4.2 Conditions Affecting Spoil Dump.....	16
4.2.1 Nature of Conditions affecting Spoil Dump	16
4.2.2 Relative Influence of Various Factors	17
4.2.3 Overall Trends - May 1989 to April 1991	19
4.2.4 Wind Speeds, High Tide Levels and Plume Occurrences.....	22
4.2.5 Specific Silt-producing Events.....	23
4.2.6 Review of Conditions producing Silt Plumes.....	26
4.3 Changes in Spoil Dump Shoreline	29
4.3.1 Shoreline Changes before September 1987	29
4.3.2 Shoreline Changes since Spoil Dump Formation.....	29
4.3.3 Synthesis of Beach Sediment Movements since December 1987.....	31
4.4 Nature of Sediments Released from Spoil Dump	33
4.4.1 General Considerations.....	33
4.4.2 Natural Beach Sediments of Heron Island.....	34
4.4.3 Sediments on Spoil Dump Beach and its Vicinity	36
4.4.4 Silt in Spoil Dump, Plume and Reef Flat Deposits.....	38

4.5	Silt Plumes	41
4.5.1	Plumes Generated during Boat Harbour Enlargement Works	41
4.5.2	Plumes Originating from Spoil Dump.....	42
4.5.3	Plumes around Island.....	43
4.6	Monitoring of Reef Flat Sediments	44
4.6.1	Sediment Distribution before 1987.....	44
4.6.2	Sediment Distribution after 1987	45
4.6.3	Synthesis of Sediment Distribution Patterns on the Reef Flat.....	46
4.7	Monitoring of Sediment-affected Beach Rock.....	46
4.8	Lithification and Vegetation of Spoil Dump Material.....	47
5.	ASSESSMENT OF OVERALL SITUATION	49
6.	CONCLUSIONS.....	52
6.1	Specific Conclusions Relating to Heron Island Spoil Dump.....	52
6.2	Some General Observations concerning Environmental Monitoring.....	52
7.	RECOMMENDATIONS.....	54
7.1	Short Term	54
7.2	Long Term.....	54
7.3	General	56
8.	ACKNOWLEDGEMENTS	57
9.	REFERENCES.....	58

TABLES

1.	Tidal Planes at Heron Island.....	12
2.	Quantity of material in spoil dump	16
3.	% Occurrence of silt plumes at station 2 for wind speeds and wave heights greater than specified values - May 1989 - April 1990.....	18
4.	% observations when silt plumes were recorded.....	20
5.	Significant silt-producing events at Heron Island -April 1989 to April 1991	28
6.	Fall velocities of silt particles.	40
7.	Species and number of individuals of plants recognised on the spoil dump at Heron Island	48

PHOTOGRAPHS

Photo 1.	Aerial view of boat harbour and spoil dump during construction - 6 October 1987 (Photo QNPWS).....	63
Photo 2.	Aerial view of completed spoil dump showing silt plume moving southeastwards along shoreline - November 1987 (Photo QNPWS).....	63
Photo 3.	Overflow from settling pond during early stage of dredging - 18(?) September 1987 (Photo Alan Smith).....	65
Photo 4.	Overflow from settling pond/spoil dump during late stage of dredging - 28-29(?) October 1987 (Photo Alan Smith).....	65
Photo 5.	Aerial view of spoil dump shortly after completion of boat harbour construction - 7 December 1987 (Photo QNPWS).....	67
Photo 6.	Silt scarp and spoil dump beach south of jetty in vicinity of station 2 - 4 April 1989 (Photo J.L.F. Hacker)	69
Photo 7.	Erosion scarp and shingle on beach face at southern end of spoil dump in vicinity of station 1 - 16 December 1988 (Photo J.S. Jell)	71
Photo 8.	Interbedded layers of silt, sand and coarser material in vicinity of station 1 - 16 December 1988 (Photo J.S. Jell)	71
Photo 9.	Waves breaking on spoil dump and creating a silt plume - 6 April 1989 (Photo J.L.F. Hacker)	73
Photo 10.	Silt plume generated from spoil dump beach - 6 April 1989 (Photo J.L.F. Hacker)	73
Photo 11.	Silt plume north of jetty following wave attack and mechanical movement of beach material to protect jetty - 29 May 1989 (Photo Andrew Flowers).....	75
Photo 12.	Localised silt plume generated by excavator working in boat harbour - 19 February 1988 (Photo QNPWS).....	75
Photo 13.	Silt plume generated by dredge working in boat harbour - 21 September 1987 (Photo QNPWS).....	77

Photo 14.	Silt plumes from dredge and spoil dump extending over southern reef flat - 23 October 1987 (Photo QNPWS)	77
Photo 15.	Silt covered beach rock on southern side of island - 10 March 1988 (Photo QNPWS)	79
Photo 16.	Western end of beach rock near spoil dump showing silt remaining on lower levels of rock - 1 December 1990 (Photo J.S. Jell)	79
Photo 17.	Dried algae-encrusted mud on beach rock - May 1988. (Photo J.S. Jell)	81
Photo 18.	Vegetation on spoil dump - 1 December 1990 (Photo J.S. Jell)	81

FIGURES

1.	Location of Heron Island	86
2.	Western end of Heron Island - Works constructed prior to 1987	87
3.	Boat Harbour Enlargement Works 1987	88
4.	Location of sediment sampling traverses	89
5.	Spoil dump - May 1988	90
6.	Spoil dump - April 1989 including location of test holes	91
7.	Spoil dump - January 1990	92
8.	Spoil dump - June 1991	93
9.	Profile in excavation at location C4	94
10.	Sections through spoil dump along borehole grid lines	95
11.	Change in spoil dump volume - December 1987 to June 1991	96
12.	Silt plume occurrences and wind speed - station 2 May 1989 - April 1990	97
13.	Silt plume occurrences and high tide level - station 2 May 1989 - April 1990	97
14.	Silt plume occurrences and 48h rainfall - station 2 May 1989 - April 1990	98

15.	Silt plume occurrences and average breaker height - station 2 May 1989 - April 1990.....	99
16.	Silt plume occurrences and average breaker height - station 1 May 1989 - April 1990.....	99
17.	Silt plume widths at station 2 May 1989 - April 1990.....	100
18.	Silt plume widths at station 1 May 1989 - April 1990.....	100
19.	Wave directions at spoil dump May 1989 - April 1990.....	101
20.	Monthly silt plume occurrences - December 1988 to April 1990.....	102
21.	Monthly rainfall - December 1988 to April 1990.....	103
22.	Monthly high tide level occurrences - December 1988 to April 1990.....	104
23.	Monthly wind speed occurrences - December 1988 to April 1990.....	105
24.	Monthly average breaker height occurrences at station 2 - December 1988 to April 1990.....	106
25.	Silt plume occurrences at station 2 for various wind speeds and high tide levels	107
26.	Reef top waves and tidal conditions.....	108
27.	Meteorological event EO - 29 March to 7 April 1989	109
28.	Meteorological event E1 - 25 May to 1 June 1989	110
29.	Meteorological event E2 - 25 to 29 July 1989.....	111
30.	Meteorological event E3 - 17 to 21 August 1989	112
31.	Meteorological event E4 - 17 to 21 September 1989.....	113
32.	Meteorological event E5 - 19 to 22 November 1989	114
33.	Meteorological event E6 - 27 to 30 November 1989	115
34.	Meteorological event E7 - 29 January to 2 February 1990.....	116
35.	Meteorological event E8 - 11 to 30 March 1990	117
36.	Meteorological event E9 - 7 to 11 June 1990	118
37.	Meteorological event E10 - 14 to 18 August 1990	119
38.	Meteorological event E11 - 1 to 5 January 1991	120

39.	Shoreline changes - 1980 to 1987	121
40.	Shoreline changes - 1987 to 1990	122
41.	Volume changes along spoil dump relative to August 1984	123
42.	Spoil dump Profiles 1 to 5	124
43.	Spoil dump Profiles 6 to 10	125
44.	Beach profiles at jetty	126
45.	Scarp recession on southern side of jetty	127
46.	Shoreline changes east of spoil dump	128
47.	Erosion - accretion pattern at spoil dump	129
48.	Spoil dump shoreline realignment	130
49.	Location of Flood's beach observation stations (Flood 1984)	131
50.	Comparison of natural beach profile and spoil dump beach profile	131
51.	Sediment sample locations in vicinity of spoil dump	132
52.	Silt plumes originating from spoil dump - effect of wind direction	133
53.	Silt plumes originating from spoil dump - effect of wave height and tide height	134
54.	Silt plumes originating from spoil dump - effect of rainfall	135
55.	Silt plume concentrations - 13 December 1988	136
56.	Distribution pattern of median size coefficients for sediments - pre 1987	137
57.	Distribution pattern of median size (graphic mean) coefficients for sediments - December 1987, 1988, 1989	138
58.	Distribution pattern of sorting (inclusive graphic standard deviation) coefficients for sediments - December 1987, 1988, 1989	139
59.	Distribution pattern of silt fraction (% of total sample) of sediments - December 1987, 1988, 1989	140
60.	Histograms of size fractions of sediments - December 1987, 1988, 1989	141

APPENDICES

A.	Heron Island Coastal Observations - Data Recording Sheets	143
B.	Coastal Observations - May 1990 to April 1991 - Figures.....	147
C.	Coastal Observations - Significant Events.....	153
D.	Specific Silt-producing Events.....	161
E.	Spoil Dump Sediment Samples - Summary	167
F.	Grain Size Distribution Curves.....	171

PART TWO Report on effects of Tropical Cyclone *Fran* March 1992

1.	INTRODUCTION	189
2.	HERON ISLAND AND TROPICAL CYCLONE <i>FRAN</i>	190
3.	INVESTIGATIONS	191
3.1	Objectives	191
3.2	Field Work	191
3.3	Sediment Analyses	191
3.4	Surveys of Spoil Dump Size and Shape	192
3.5	Hydraulic and Meteorological Data Analyses.....	192
4.	RESULTS OF ANALYSES	193
4.1	Conditions affecting Spoil Dump during Tropical Cyclone <i>Fran</i>	193
4.1.1	Cyclonic Conditions affecting Coral Cay Beaches	193
4.1.2	Specific Conditions during Tropical Cyclone <i>Fran</i>	193
4.2	Quantity of Material in Spoil Dump.....	195
4.3	Changes in Spoil Dump Shoreline during Tropical Cyclone <i>Fran</i>	196
4.4	Changes in Reef-flat Sediments.	197
5.	CONCLUSIONS	198
6.	RECOMMENDATIONS.....	200
7.	ACKNOWLEDGEMENTS	201
8.	REFERENCES	202

FIGURES

1.	Location of Heron Island	205
2.	Location of spoil dump and observation stations.....	206
3.	Reef top waves and tidal conditions.....	207
4.	Track of tropical cyclone <i>Fran</i> , 11 to 17 March 1992.	208
5.	Tropical cyclone <i>Fran</i> event, 6 to 20 March 1992.....	209
6.	Spoil dump - April 1992.....	210
7.	Changes in spoil dump volume - December 1987 to April 1992.....	211
8.	Volume of material in extended spoil dump area (including four extra profiles east of spoil dump) - December 1987 to April 1992.	212
9.	Volume changes along spoil dump relative to August 1984	213
10.	Spoil dump profiles 1 to 5.	214
11.	Spoil dump profiles 6 to 10.	215
12.	Beach profiles at jetty.	216
13.	Erosion scarp position along southern side of jetty.....	217
14.	Distribution pattern of median size (graphic mean) coefficients for sediments - December 1989 and April 1992.	218
15.	Distribution pattern of sorting (inclusive graphic standard deviation) coefficients for sediments - December 1989 and April 1992.	219
16.	Distribution pattern of silt fraction (% of total sample) of sediments - December 1989 and April 1992.	220
17.	Distribution of median size (graphic mean) and silt and clay content of harbour and channel - December 1989 and April 1992.....	221